



These two sprinkler heads were removed from a working golf course. The head on the left was not treated with ozone, while the head on the right was treated with ozone.

Note: both were distributing reclaimed water from the same source